Product Data Sheet

Thermo-Hygrometer Outdoor Sensor
Reference 91000-006/B

Specifications

- -50+70°C / -58+158°F / 20-99% RH
- Resolution: 0.1° / 1% RH
- Accuracy: ±1°C / ±2°F / ±3% RH
- **Thermometer functions:** MAX/MIN - IN/OUT
- **Hygrometer function:** INDOOR
- Double display
- Cable: 200 cm
- 1 AAA battery
- In BIOTEMP blister



Instructions

Insert the battery to start the unit.
Press [°C/°F] once to select the measure unit.

IN-OUT FUNCTION
Press [IN/OUT] to display outdoor temperature.
Press [IN/OUT] again to display normal temperature.

MAX/MIN MEMORY DISPLAY
Press [MAX/MIN] to display the maximum temperature and humidity.
Press [MAX/MIN] to display the minimum temperature and humidity.
Press [MAX/MIN] all over again to read the ambient temperature.
Press [CLEAR] to reset Max/Min memory.

Do not use inside oven or microwave oven. Do not wash in a dish washer. If the display becomes dim, replace the battery.

Alla France
Z.I. du Bompas - 13, rue du Bompas - Chemillé - 49120 Chemillé-en-Anjou - FRANCE
Tél. + 33 (0)2 41 30 55 08 - Fax +33 (0)2 41 30 34 67
www.allafrance.com